10/65/914

Attorney Docket No.: 108298709US

I hereby certify that this correspondence is being deposited with the U.S. Postal Service with sufficient postage as First Class Mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450. on:

October 6, 2005 Date: \_

OCT 1 1 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

TRADEM RE APPLICATION OF: SUAN JEUNG BOON et al.

6.882.021 B2

ISSUED:

PATENT No.:

**APRIL 19, 2005** 

FOR: PACKAGED IMAGE SENSING MICROELECTRONIC DEVICES

INCLUDING A LEAD AND METHODS OF

PACKAGING IMAGE SENSING **MICROELECTRONIC DEVICES** 

**INCLUDING A LEAD** 

EXAMINER:

**KEVIN QUINTO** 

**PATENT** 

ART UNIT:

2826

CONF. No.: 9566

**Request for Certificate of Correction** under 37 C.F.R. §1.322 or §1.323

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

- 1. The applicant(s) requests a Certificate of Correction to correct errors in the above-identified patent, which are listed on the enclosed Form PTO/SB/44.
- Any errors on the part of the applicant are of a clerical or typographical nature or 2. are otherwise minor in character. None of the requested corrections would constitute new matter or require reexamination of the patent.
- 3. Source of Error(s) and Payment of Fee:
  - All of the errors listed on Form PTO/SB/44 are believed to be due to  $\boxtimes$ mistake on the part of the USPTO (37 C.F.R. §1.322). Accordingly, no fees are believed to be due.
  - At least one of the errors occurred due to applicant's mistake made in good faith (37 C.F.R. §1.323).

		A check covering the fee under 37 C.F.R. §1.20(a) (\$100.00) is enclosed herewith.
		Please charge the fee under 37 C.F.R. §1.20(a) to Deposit Account No. 50-0665. This paper is provided in triplicate.
		Please charge any underpayment necessary for consideration of this paper to Deposit Account No. 50-0665.
4.	Please send the Certificate of Correction to the undersigned at the address shown below.	
		Respectfully submitted,
		Perkins Coie LLP
Date:_	10/	3/05 Dael Det
		David T. Dutcher Registration No. 51,638
Correspondence Address:		

Customer No. 25096

Customer No. 25096
Perkins Coie LLP
P.O. Box 1247
Seattle, Washington 98111-1247
(206) 359-8000

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,882,021 B 2

**DATED:** April 19, 2005

INVENTOR(S): Suan Jeung Boon et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7 Line 66, "end" should be --ends--;

Line 19, insert --an-- between "defines" and "axis";

MAILING ADDRESS OF SENDER:

Perkins Coie LLP PATENT-SEA PO Box 1247 Seattle, WA 98111-1247 PATENT NO. 6,882,021

No. of additional copies

**≕>** ¹

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, Washington, DC 20231.